



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

PROJECT DETAILS

Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
None	
Pond Locations	https://imageshack.com...

MAINTENANCE LOG

Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	07/26/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

Dam



Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

Outlet



Additional Notes

Invasive vegetation in the outlet area was treated. Water level was above drawdown height upon arrival but seems to be draining efficiently.

Pond Name	WP 1
Access Address	400 Market St, Chaple Hill, NC
Service Date	07/26/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

Dam



Riser



Inlet





PO Box 1089
 Apex NC 27502
 919-851-0033

Client Log - Triangle

Date: 08/03/2018

Outlet



Additional Notes

Water level was above drawdown height upon arrival but seems to be draining efficiently as shown in image 1. Pond was treated aggressively for invasive aquatic vegetation. Invasive vegetation in the outlet area was also treated. The addition of an aerator system would likely improve overall water quality.

Noted Image 1



Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	07/26/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

Overview of the pond



Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

Inlet



Outlet



Additional Notes

Image 1 shows erosion caused by an additional inlet source where rip rap may be needed. Images 2 and 3 show before and after rip rap was rearranged to cover exposed matting. Images 4-6 show the additional inlets. Image 7 shows bare soil on the slope where vegetation is needed. Invasive vegetation in the rip rap was treated. Water level was above drawdown height upon arrival but seems to be draining efficiently.

Noted Image 1





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

Noted Image 2



Noted Image 3



Image 4





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

Image 5



Image 6



Image 7



Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	07/26/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

Outlet Service

SC= Service Completed

Unclog Drain

NN= Service Not Needed

Clean Riser/Trash rack

SC= Service Completed

Add Dye?

NN= Service Not Needed

Fountain/Aerator Condition

FF= Fully Functional

Mow/Weed eat

NN= Service Not Needed

Overview of the pond



Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

Inlet



Outlet



Additional Notes

Road barrier cover was found floating in the center of the pond upon arrival. Images 1 and 2 show before and after barrier was put back after being removed from the pond. Note there is a lock on the gate as shown in image 3 - combination is needed for equipment access. Invasive vegetation in the rip rap was treated.

Noted Image 1





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 08/03/2018

Noted Image 2



Noted Image 3



HANDOFF SCREEN

Press next to upload submission