



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 08/31/2018

## PROJECT DETAILS

### Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #5150	
Pond Locations	<a href="https://imageshack.com...">https://imageshack.com...</a>

## MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chaple Hill, NC
Service Date	08/29/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 08/31/2018

Dam



Riser



Inlet





PO Box 1089  
 Apex NC 27502  
 919-851-0033

Client Log - Triangle

Date: 08/31/2018

Outlet



**Additional Notes**

Treated aggressively for invasive aquatic vegetation. Treated the rip rap for invasive vegetation. Image of the dam shows bare soil spots where vegetation is needed. Image 1 shows where mowing is needed above the outlet.

Noted Image 1



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	08/29/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	WN= Work Needed



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 08/31/2018

Overview of the pond



Dam



Riser





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 08/31/2018

Inlet



Outlet



Additional Notes

Treated for invasive vegetation in the rip rap. Image of the dam shows bare soil spots where vegetation is needed. Image of the outlet shows bare soil on the side of the pipe. Water level was below drawdown height upon arrival. Noted image 1 shows leaks in the horizontal outlet pipe. Noted Image 1



Pond Name

WP 3

Access Address

400 Market St, Chaple Hill, NC



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 08/31/2018

Service Date	08/29/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	WN= Work Needed
Overview of the pond	



Dam





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 08/31/2018

Riser



Inlet



Outlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 08/31/2018

Additional Notes

Treated for invasive vegetation in the rip rap. Mowing is needed on the site. Noted image 1 shows a fallen tree that is limiting access to the outlet. Noted image 2 shows exposed matting in the inlet rip rap where additional material is needed to cover completely. Noted images 3 and 4 show the additional inlets.

Noted Image 1



Noted Image 2



Noted Image 3





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 08/31/2018

Image 4



Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	08/29/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 08/31/2018

Dam



Riser



Inlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 08/31/2018

Outlet



Additional Notes

Image 1 shows the additional inlet. Pond was treated for algae. Invasive vegetation in the rip rap was treated.  
Noted Image 1



HANDOFF SCREEN

Press next to upload submission