



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

PROJECT DETAILS

Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #5150	
Pond Locations	https://imageshack.com...

MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chapel Hill, NC
Service Date	09/20/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	N/A= Not Applicable
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Inlet



Outlet



Additional Notes

Riprap along outlet treated
Noted images 1 and 2 show before and after riser was cleaned of debris
There was no watermeal in the pond during this visit.
A large amount of thatch, tree limbs, and other organic debris washed in with the recent rain.
Larger limbs and trash were removed from the site.
Mowing is needed above the outlet as seen in image 3.
Noted Image 1





PO Box 1089
 Apex NC 27502
 919-851-0033

Client Log - Triangle

Date: 09/21/2018

Noted Image 2



Noted Image 3



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	09/20/2018
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	SC= Service Completed
Mow/Weed eat	WN= Work Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Overview of the pond



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Outlet



Additional Notes

- Backside of dam needs mowed
- Bare soil on backside of dam, visible in outlet picture
- Aerator was not running, reset gfci and is running again

Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	09/20/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	WN= Work Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Inlet



Outlet



Additional Notes

Noted image 1 shows secondary inlet and washed out rip rap / exposed matting material where additional rip rap is needed

Noted image 2 shows fallen tree on back of dam limiting access to the outlet

Back of the dam needs to be mowed

Saplings inside the buffer were removed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	09/20/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Riser



Inlet



Outlet



Additional Notes

Rip rap in the outlet area was treated
Noted image 1 shows a secondary inlet



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/21/2018

Noted Image 1



HANDOFF SCREEN

Press next to upload submission