



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

## PROJECT DETAILS

### Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #5150	
Pond Locations	<a href="https://imageshack.com...">https://imageshack.com...</a>

## MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chaple Hill, NC
Service Date	05/17/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Dam



Riser





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Inlet



Outlet



Additional Notes

Removed trash from system. Noted image 1 shows additional riser. Noted images 2, 3, 4 show erosion on dam.

Noted Image 1





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Noted Image 2



Noted Image 3





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Image 4



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	05/17/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	NN= Service Not Needed



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Overview of the pond

---



Dam

---





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Riser



Inlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Outlet



**Additional Notes**

Removed trash from system. Noted images 1, 2, and 3 show erosion on dam. Noted image 4 shows erosion on shoreline at riser. Noted image 5 shows erosion on outlet. Noted image 6 shows erosion on shoreline.



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Noted Image 1



Noted Image 2





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Noted Image 3



Image 4





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Image 5



Image 6





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	05/17/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	



Dam





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Riser



Inlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Outlet



**Additional Notes**

Removed trash from system. Noted images 1, 2, and 3 show additional inlets. Noted image 4 shows large bare area in inlet rip rap that needs repair. Noted images 5, 6, and 7 show erosion on dam. Noted image 8 shows sediment buildup in inlet.  
Noted Image 1





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Noted Image 2



Noted Image 3



Image 4





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Image 5



Image 6





PO Box 1089  
 Apex NC 27502  
 919-851-0033

Client Log - Triangle

Date: 05/21/2019

Image 7



Image 8



Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	05/17/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	NN= Service Not Needed



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Overview of the pond

---



Dam

---





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Riser



Inlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Outlet



Additional Notes

Removed trash from system. Treated for saplings in buffer.

Noted images 1 and 2 show erosion on dam. Noted image 3 shows erosion on back side of dam.



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Noted Image 1



Noted Image 2





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 05/21/2019

Noted Image 3



## HANDOFF SCREEN

Press next to upload submission