



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

## PROJECT DETAILS

### Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #5150	
Pond Locations	<a href="https://imageshack.com...">https://imageshack.com...</a>

## MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chaple Hill, NC
Service Date	06/27/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Dam



Riser





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Inlet



Outlet



#### Additional Notes

Removed trash from the system.  
Treated woody vegetation growing in the buffer. Trace amounts of watermeal observed in the pond. The watermeal was not currently at a nuisance level and therefore no treatment was needed.  
Noted image 1 shows exposed soil on the dam. Noted image 2 shows extensive erosion below the outlet.



PO Box 1089  
 Apex NC 27502  
 919-851-0033

Client Log - Triangle

Date: 07/10/2019

Noted Image 1



Noted Image 2



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	06/27/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Fountain/Aerator Condition  
Mow/Weed eat  
Overview of the pond

FF= Fully Functional  
NN= Service Not Needed



Dam





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Riser



Inlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Outlet



Additional Notes

Removed trash from the system.

Trace amounts of watermeal observed in the pond. Noted image 1 shows an additional inlet.



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Noted Image 1



Noted Image 2





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Noted Image 3



Image 4





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Image 5



Image 6



Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	06/27/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Fountain/Aerator Condition  
Mow/Weed eat  
Overview of the pond

WN= Work Needed  
NN= Service Not Needed



Dam





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Riser



Inlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Outlet



Additional Notes

- Removed trash from the system.
- Treated filamentous algae growing along the shoreline.
- Treated woody vegetation growing in the buffer. Noted image 1 shows an additional inlet.
- Noted image 2 shows erosion on backside of the dam.



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Noted Image 1



Noted Image 2





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	06/27/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	WN= Work Needed
Overview of the pond	



Dam





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Riser



Inlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Outlet



Additional Notes

Removed trash from the system. Noted image 1 shows an additional inlet. Noted image 2 shows a rip-rap inlet. Noted image 3 shows a large washed out area in the rip-rap inlet.



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Noted Image 1



Noted Image 2





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 07/10/2019

Noted Image 3



HANDOFF SCREEN

Press next to upload submission