



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

PROJECT DETAILS

Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #2020	
Pond Locations	https://imageshack.com...

MAINTENANCE LOG

Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	07/19/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	WN= Work Needed
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Inlet



Outlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Additional Notes

Removed the trash from the system. Electrical work needed to repair the aeration unit. Treated for terrestrial vegetation in the outlet riprap. Treated for saplings in the buffer. Treated for filamentous algae along the shoreline. Noted image 1 shows an additional inlet.

Noted Image 1



Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	07/19/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	WN= Work Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Overview of the pond



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Outlet



Additional Notes

Removed the trash from the system. The dam near the outlet needs mowing to allow better access. Continue to monitor for erosion on the shoreline from previously high water. Treated for terrestrial vegetation in the inlet riprap. Treated for saplings in the buffer. Noted image 1 shows an additional inlet. Noted image 2 shows a spillway inlet that needs riprap repair. Noted image 3 shows a natural inlet with large bare spots in the riprap that needs repair.



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Noted Image 1



Noted Image 2





PO Box 1089
 Apex NC 27502
 919-851-0033

Client Log - Triangle

Date: 09/13/2019

Noted Image 3



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	07/19/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	NN= Service Not Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Overview of the pond



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Outlet



Additional Notes

Removed the trash from the system. The dam is exhibiting mild to moderate erosion on the slope opposite of the walking path. Continue to monitor for erosion on the shoreline from previously high water. Treated for watermeal along the shoreline. Noted image 1 shows erosion on the dam.
Noted Image 1



Pond Name	WP 1
Access Address	400 Market St, Chaple Hill, NC
Service Date	07/19/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Outlet Service

SC= Service Completed

Unclog Drain

NN= Service Not Needed

Clean Riser/Trash rack

SC= Service Completed

Add Dye?

NN= Service Not Needed

Fountain/Aerator Condition

N/A= Not Applicable

Mow/Weed eat

NN= Service Not Needed

Overview of the pond



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Outlet



Additional Notes

Removed the trash from the system. Continue to monitor for erosion on the shoreline from previously high water. Treated for watermeal throughout the pond basin. Treated for duckweed throughout pond basin. Treated for saplings in buffer. Treated for terrestrial vegetation in outlet riprap. Noted image 1 shows an additional riser. Noted image 2 shows erosion on the dam. Noted image 3 shows erosion on the shoreline.



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/13/2019

Noted Image 3



HANDOFF SCREEN

Press next to upload submission