



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

PROJECT DETAILS

Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #2020	
Pond Locations	https://imageshack.com...

MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chapel Hill, NC
Service Date	09/16/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Dam



Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Outlet



Additional Notes

Trash was removed from the system and the wet pond was treated for planktonic algae and Watermeal. Recommend a Sonar treatment in the future for better control. Noted image 1 shows a secondary inlet. Noted images 2 and 3 show sedimentation at the creek inlet. Noted image 4 shows exposed soil along the shoreline due to extended periods of high water. Noted image 5 shows a secondary outlet.

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Noted Image 3



Image 4





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Image 5



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	09/16/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	SC= Service Completed
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Dam



Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Outlet



Additional Notes

Trash was removed from the system and the pond was treated for planktonic algae. The air filter was cleaned for the compressor. Recommend replacing the air filter to improve functionality. Noted image 1 shows a secondary inlet. Noted image 2 shows exposed soil along the pond slope near the road. Noted image 3 shows the air filter for the aeration compressor. Noted image 4 shows exposed soil. Noted image 5 shows exposed soil along the pond slope due to extended periods of high water. Noted image 6 shows exposed aeration lines.

Noted Image 1





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Noted Image 2



Noted Image 3





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Image 4



Image 5



Image 6



Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	09/16/2019
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	SC= Service Completed
Mow/Weed eat	SC= Service Completed
Overview of the pond	



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Riser



Inlet



Outlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Additional Notes

Trash was removed from the system and the air compressor filter was cleaned. Recommend replacing the filter. Noted image 1 shows a secondary inlet. Noted image 2 shows exposed soil. Noted image 3 shows the air filter for the aeration system. Noted image 4 shows an area recommended to be weed eaten.

Noted Image 1



Noted Image 2





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Noted Image 3



Image 4



Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	09/16/2019
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	N/A= Not Applicable



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Fountain/Aerator Condition
Mow/Weed eat
Overview of the pond

N/A= Not Applicable
NN= Service Not Needed



Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Inlet



Outlet



Additional Notes

Trash was removed from the system and the pond was treated for planktonic algae. Sediment build up at the creek inlet. Noted images 1 and 2 show secondary inlets. Noted image 3 shows the creek inlet with sedimentation. Noted image 4 shows shows sedimentation at the corrugated pipe inlet. Noted image 5 shows a fallen tree at the outlet. Noted image 6 shows a secondary inlet. Noted image 7 shows exposed soil along the shoreline due to extended periods of high water.

Noted Image 1





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Noted Image 2



Noted Image 3





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Image 4



Image 5





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 09/18/2019

Image 6



Image 7

