



Dragonfly Pond Works
 1-877-POND-WRX
 info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

PROJECT DETAILS

Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Adam Jones
Client Email Address	adam@millhouseproperties.com
Client Email Address 2	
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #2020	
Pond Locations	https://imageshack.com...

MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chaple Hill, NC
Service Date	01/09/2020
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Dam



Riser





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Inlet



Outlet





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Additional Notes

Trash was removed from the system. Images 1 and 2 show bare soil on the shoreline. Image 3 shows sediment build up near inlet. Image 4 shows erosion on the slope near the inlet. Image 5 shows minor shoreline erosion along pond slope. Image 6 shows an additional inlet by the riser. Noted Image 1





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Noted Image 2



Noted Image 3





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Image 4



Image 5





Image 6



Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	01/09/2020
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	NN= Service Not Needed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed



Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Overview of the pond



Dam





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Riser



Inlet





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Outlet



Additional Notes

Trash was removed from the system. Image 1 shows bare soil around the shoreline. Image 2 shows the compressor box. Image 3 shows a large rut on the slope near the road.



Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Noted Image 1



Noted Image 2





Noted Image 3



Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	01/09/2020
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	SC= Service Completed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed



Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Overview of the pond



Dam





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Riser



Inlet





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Outlet



Additional Notes

Trash was removed from from the system. Image 1 shows channeling to the right of the primary inlet. Images 2-4 show secondary inlets. Image 5 shows exposed soil on backside of the dam. Image 6-7 show before and after unclogging the drawdown in the riser.



Noted Image 1



Noted Image 2





Noted Image 3



Image 4





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Image 5



Image 6





Image 7



Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	01/09/2020
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	NN= Service Not Needed
Mow/Weed eat	NN= Service Not Needed



Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Overview of the pond



Dam





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Riser



Inlet





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Outlet



Additional Notes

Trash was removed from the system. Images 1-2 show secondary inlets. Images 3-4 show areas of shoreline erosion.



Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Noted Image 1



Noted Image 2





Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Client Log - Triangle

Date: 02/28/2020

Noted Image 3



Image 4



HANDOFF SCREEN

Press next to upload submission