



## Maintenance Log Triangle

---

### DRAGONFLY MAINTENANCE REPORT

---

#### Project Details

Property	SOUTHERN VILLAGE
Service Date	04/23/2021
Crew Member(s)	GW
Client Name	Adam Jones
Client Email Address	adam@millhouseproperties.com
Client Email Address 2	patsy@millhouseproperties.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Lock combination for Wet Pond #4 is 5150	
Pond Locations	<a href="https://imageshack.com...">https://imageshack.com...</a>

#### Code Types

- SC= Service Completed - Means a service or review has been completed and is in good working order.
- M= Monitoring (for any potential future problems) - Means that we may continue to review and note on regular reports. This does NOT mean there is an issue or any additional work is needed at this time.
- WN= Work Needed - Means there is work needed outside the normal scope of maintenance
- N/A= Not Applicable - Means nothing is found to be noted, there are no issues.
- NN= Not Needed - Means this has been investigated and found that no work is currently needed.

### MAINTENANCE LOG

---

Pond Name	WP 1
Access Address	1200 Highgrove Dr Chapel Hill, NC 27516
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Invasives Treated (where applicable)	Terrestrial weeds and filamentous algae
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	M= Monitoring (for any potential future problems)
Clean Riser/Trash rack	M= Monitoring (for any potential future problems)
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	M= Monitoring (for any potential future problems)

## Maintenance Log Triangle

---

Overview of the pond



Dam



Riser



Maintenance Log Triangle

---

Inlet



Outlet




## Maintenance Log Triangle

---

### Additional Notes

Removed trash from the system and treated terrestrial weeds and filamentous algae. Noted image 1 shows the creek inlet. System would benefit from mowing.



Pond Name	WP 2
Access Address	600 Brookgreen Dr Chapel Hill, NC 27516
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Invasives Treated (where applicable)	Terrestrial weeds, woody vegetation, and filamentous algae
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	M= Monitoring (for any potential future problems)
Clean Riser/Trash rack	M= Monitoring (for any potential future problems)
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	M= Monitoring (for any potential future problems)
Mow/Weed eat	M= Monitoring (for any potential future problems)
Overview of the pond	



Maintenance Log Triangle

---

Dam



Riser



Maintenance Log Triangle

---

Inlet



Outlet



## Maintenance Log Triangle

---

### Additional Notes

Removed trash from the system and treated an abundance of woody vegetation and small saplings. Also treated terrestrial weeds and filamentous algae.

Pond Name	WP 3
Access Address	111 Parkside Cir Chapel Hill, NC 27516
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Invasives Treated (where applicable)	Terrestrial weeds and woody vegetation
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	M= Monitoring (for any potential future problems)
Clean Riser/Trash rack	M= Monitoring (for any potential future problems)
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	M= Monitoring (for any potential future problems)
Overview of the pond	



### Dam



Maintenance Log Triangle

---

Riser



Inlet







Maintenance Log Triangle

Outlet



Additional Notes

Removed trash from the system and blew debris from the riprap inlet. Noted images 1 and 2 show additional inlets. Noted image 3 shows the riprap inlet; note the washout of the rocks and the exposed fabric.



Pond Name	WP 4
Access Address	501 Kildaire Rd, Chapel Hill, NC 27516
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Invasives Treated (where applicable)	Terrestrial weeds and woody vegetation
Inlet service	SC= Service Completed

Maintenance Log Triangle

Outlet Service	SC= Service Completed
Unclog Drain	M= Monitoring (for any potential future problems)
Clean Riser/Trash rack	M= Monitoring (for any potential future problems)
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	M= Monitoring (for any potential future problems)
Mow/Weed eat	M= Monitoring (for any potential future problems)
Overview of the pond	M= Monitoring (for any potential future problems)



Dam



## Maintenance Log Triangle

---

Riser



Inlet



## Maintenance Log Triangle

---

Outlet



### Additional Notes

Removed trash from the system and treated terrestrial weeds and wood vegetation. Noted images 1 and 2 show additional submerged inlets.



Noted Image 1



Noted Image 2