



Maintenance Log Triangle

DRAGONFLY MAINTENANCE REPORT

Project Details

| | |
|--|---|
| Property | SOUTHERN VILLAGE |
| Service Date | 07/26/2021 |
| Crew Member(s) | GW |
| Client Name | Adam Jones |
| Client Email Address | adam@millhouseproperties.com |
| Client Email Address 2 | patsy@millhouseproperties.com |
| Client Email Address 3 | |
| Client Email Address 4 | |
| Number of Ponds & Pond Type | 4 Wet Ponds |
| Mowing Schedule | 2 Mowings Per Year |
| Mowing Service | |
| Mowing occurs inside of the fence. | |
| Special Instructions | |
| Lock combination for Wet Pond #4 is 5150 | |
| Pond Locations | https://imageshack.com... |

Code Types

- SC= Service Completed - Means a service or review has been completed and is in good working order.
- M= Monitoring (for any potential future problems) - Means that we may continue to review and note on regular reports. This does NOT mean there is an issue or any additional work is needed at this time.
- WN= Work Needed - Means there is work needed outside the normal scope of maintenance
- N/A= Not Applicable - Means nothing is found to be noted, there are no issues.
- NN= Not Needed - Means this has been investigated and found that no work is currently needed.

MAINTENANCE LOG

| | |
|--------------------------------------|---|
| Pond Name | WP 1 |
| Access Address | 1200 Highgrove Dr Chapel Hill, NC 27516 |
| Trash Pickup | SC= Service Completed |
| Treat Invasives | SC= Service Completed |
| Invasives Treated (where applicable) | Terrestrial weeds and woody vegetation |
| Inlet service | SC= Service Completed |
| Outlet Service | SC= Service Completed |
| Unclog Drain | M= Monitoring (for any potential future problems) |
| Clean Riser/Trash rack | M= Monitoring (for any potential future problems) |
| Add Dye? | N/A= Not Applicable |
| Fountain/Aerator Condition | N/A= Not Applicable |
| Mow/Weed eat | M= Monitoring (for any potential future problems) |



Maintenance Log Triangle

Overview of the pond



Dam



Maintenance Log Triangle

Riser



Inlet



Maintenance Log Triangle

Outlet



Additional Notes

Removed trash from the system and treated terrestrial weeds and woody vegetation. Noted image 1 shows an additional creek inlet.



| | |
|--------------------------------------|---|
| Pond Name | WP 2 |
| Access Address | 600 Brookgreen Dr Chapel Hill, NC 27516 |
| Trash Pickup | SC= Service Completed |
| Treat Invasives | SC= Service Completed |
| Invasives Treated (where applicable) | Woody vegetation and planktonic algae |
| Inlet service | SC= Service Completed |
| Outlet Service | SC= Service Completed |

Maintenance Log Triangle

Unclog Drain

M= Monitoring (for any potential future problems)

Clean Riser/Trash rack

M= Monitoring (for any potential future problems)

Add Dye?

N/A= Not Applicable

Fountain/Aerator Condition

M= Monitoring (for any potential future problems)

Mow/Weed eat

M= Monitoring (for any potential future problems)

Overview of the pond



Dam



Maintenance Log Triangle

Riser



Inlet



Maintenance Log Triangle

Outlet



Additional Notes

Removed trash from the system and treated woody vegetation and planktonic algae.

| | |
|--------------------------------------|---|
| Pond Name | WP 3 |
| Access Address | 111 Parkside Cir Chapel Hill, NC 27516 |
| Trash Pickup | SC= Service Completed |
| Treat Invasives | SC= Service Completed |
| Invasives Treated (where applicable) | Terrestrial weeds and woody vegetation |
| Inlet service | SC= Service Completed |
| Outlet Service | SC= Service Completed |
| Unclog Drain | M= Monitoring (for any potential future problems) |
| Clean Riser/Trash rack | M= Monitoring (for any potential future problems) |
| Add Dye? | N/A= Not Applicable |
| Fountain/Aerator Condition | N/A= Not Applicable |
| Mow/Weed eat | WN= Work Needed |

Maintenance Log Triangle

Overview of the pond



Dam



Maintenance Log Triangle

Riser



Inlet




Maintenance Log Triangle

Outlet



Additional Notes

Removed trash from the system and treated terrestrial weeds and woody vegetation. System would benefit from more frequent mowing. Noted image 1 shows an additional inlet with exposed fabric. Noted images 2 and 3 show additional inlets.



| | |
|--------------------------------------|--|
| Pond Name | WP 4 |
| Access Address | 501 Kildaire Rd, Chapel Hill, NC 27516 |
| Trash Pickup | SC= Service Completed |
| Treat Invasives | SC= Service Completed |
| Invasives Treated (where applicable) | Terrestrial weeds, woody vegetation, and filamentous algae |

Maintenance Log Triangle

| | |
|----------------------------|---|
| Inlet service | SC= Service Completed |
| Outlet Service | SC= Service Completed |
| Unclog Drain | M= Monitoring (for any potential future problems) |
| Clean Riser/Trash rack | M= Monitoring (for any potential future problems) |
| Add Dye? | N/A= Not Applicable |
| Fountain/Aerator Condition | M= Monitoring (for any potential future problems) |
| Mow/Weed eat | M= Monitoring (for any potential future problems) |
| Overview of the pond | M= Monitoring (for any potential future problems) |



Dam



Maintenance Log Triangle

Riser



Inlet



Maintenance Log Triangle

Outlet



Additional Notes

Removed trash from the system and treated terrestrial weeds, woody vegetation, and filamentous algae. Noted image 1 shows an additional inlet.



Noted Image 1