



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

PROJECT DETAILS

Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #5150	
Pond Locations	https://imageshack.com...

MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chapel Hill, NC
Service Date	10/01/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Dam



Riser





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Inlet



Outlet



Additional Notes

- Pond treated for watermeal
- Pond treated for algae

Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	10/24/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	NN= Service Not Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Overview of the pond



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Riser



Inlet





PO Box 1089
 Apex NC 27502
 919-851-0033

Client Log - Triangle

Date: 10/28/2018

Outlet



Additional Notes

Pond treated for invasive vegetation
 Pond treated for algae

Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	10/24/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	WN= Work Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Overview of the pond



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Outlet



Additional Notes

Noted image 1 shows fallen tree over outlet riprap and on back of dam
Noted image 2 shows secondary inlet
Edges of pond severely overgrown
Back of dam overgrown
Pond treated for invasive vegetation
Riprap along inlets and outlet treated
Noted Image 1





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Noted Image 2



Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	10/24/2018
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	NN= Service Not Needed



PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Overview of the pond



Dam





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Riser



Inlet





PO Box 1089
Apex NC 27502
919-851-0033

Client Log - Triangle

Date: 10/28/2018

Outlet



Additional Notes

Noted image 1 shows secondary inlet
Pond treated for invasive vegetation
Riprap along inlet and outlet treated
Pond treated for algae
Noted Image 1



HANDOFF SCREEN

Press next to upload submission