



PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 12/21/2018

## PROJECT DETAILS

### Dragonfly Maintenance Report

Property	SOUTHERN VILLAGE
Client Name	Patsy Smith, Tony Smith
Client Email Address	patsysmith7077@gmail.com
Client Email Address 2	tony@berkeleychapelhill.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Service Type	
Standard	
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #5150	
Pond Locations	<a href="https://imageshack.com...">https://imageshack.com...</a>

## MAINTENANCE LOG

Pond Name	WP 1
Access Address	400 Market St, Chapel Hill, NC
Service Date	12/21/2018
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 12/21/2018

Dam



Riser





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 12/21/2018

Inlet



Outlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 12/21/2018

Additional Notes

There were no invasive species present in the pond.

Pond Name	WP 2
Access Address	400 Market St, Chaple Hill, NC
Service Date	12/21/2018
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	



Dam





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 12/21/2018

Riser



Outlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 12/21/2018

Additional Notes

There were no invasive species present in the pond. Unable to locate inlet pipe due to high water level.

Pond Name	WP 3
Access Address	400 Market St, Chaple Hill, NC
Service Date	12/21/2018
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	



Dam





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 12/21/2018

Riser



Inlet





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 12/21/2018

Outlet



Additional Notes

There were no invasive species present in the pond. Rearranged rip rap in the inlet area to cover exposed matting.

Pond Name	WP 4
Access Address	400 Market St, Chaple Hill, NC
Service Date	12/21/2018
Trash Pickup	SC= Service Completed
Treat Invasives	NN= Service Not Needed
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	NN= Service Not Needed
Clean Riser/Trash rack	SC= Service Completed
Add Dye?	NN= Service Not Needed
Fountain/Aerator Condition	FF= Fully Functional
Mow/Weed eat	NN= Service Not Needed
Overview of the pond	





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 12/21/2018

Dam



Riser





PO Box 1089  
Apex NC 27502  
919-851-0033

Client Log - Triangle

Date: 12/21/2018

Outlet



Additional Notes

There were no invasive species present in the pond. Unable to locate inlet pipe due to high water level.

**HANDOFF SCREEN**

Press next to upload submission