



Maintenance Log Triangle

DRAGONFLY MAINTENANCE REPORT

Project Details

Property	SOUTHERN VILLAGE
Service Date	03/17/2021
Crew Member(s)	GW
Client Name	Adam Jones
Client Email Address	adam@millhouseproperties.com
Client Email Address 2	patsy@millhouseproperties.com
Client Email Address 3	
Client Email Address 4	
Number of Ponds & Pond Type	4 Wet Ponds
Mowing Schedule	2 Mowings Per Year
Mowing Service	
Mowing occurs inside of the fence.	
Special Instructions	
Pond 4 #1234	
Pond Locations	https://imageshack.com...

Code Types

- SC= Service Completed - Means a service or review has been completed and is in good working order.
- M= Monitoring (for any potential future problems) - Means that we may continue to review and note on regular reports. This does NOT mean there is an issue or any additional work is needed at this time.
- WN= Work Needed - Means there is work needed outside the normal scope of maintenance
- N/A= Not Applicable - Means nothing is found to be noted, there are no issues.
- NN= Not Needed - Means this has been investigated and found that no work is currently needed.

MAINTENANCE LOG

Pond Name	WP 1
Access Address	1200 Highgrove Dr Chapel Hill, NC 27516
Trash Pickup	SC= Service Completed
Treat Invasives	M= Monitoring (for any potential future problems)
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	M= Monitoring (for any potential future problems)
Clean Riser/Trash rack	M= Monitoring (for any potential future problems)
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	M= Monitoring (for any potential future problems)



Maintenance Log Triangle

Overview of the pond



Dam



Riser



Maintenance Log Triangle

Inlet



Outlet





Maintenance Log Triangle

Additional Notes

Removed trash from the system and opened manhole to inspect the riser. Note the sediment from the creek inlet in the inlet image.

Pond Name	WP 2
Access Address	600 Brookgreen Dr Chapel Hill, NC 27516
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Invasives Treated (where applicable)	Filamentous algae
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	M= Monitoring (for any potential future problems)
Clean Riser/Trash rack	M= Monitoring (for any potential future problems)
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	M= Monitoring (for any potential future problems)
Mow/Weed eat	M= Monitoring (for any potential future problems)
Overview of the pond	M= Monitoring (for any potential future problems)



Dam



Maintenance Log Triangle

Riser



Inlet



Maintenance Log Triangle

Outlet



Additional Notes

Removed trash from the system and treated filamentous algae.

Pond Name	WP 3
Access Address	111 Parkside Cir Chapel Hill, NC 27516
Trash Pickup	SC= Service Completed
Treat Invasives	SC= Service Completed
Invasives Treated (where applicable)	Terrestrial weeds
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed
Unclog Drain	M= Monitoring (for any potential future problems)
Clean Riser/Trash rack	M= Monitoring (for any potential future problems)
Add Dye?	N/A= Not Applicable
Fountain/Aerator Condition	N/A= Not Applicable
Mow/Weed eat	M= Monitoring (for any potential future problems)



Dragonfly Pond Works
1-877-POND-WRX
info@dragonflypondworks.com

Maintenance Log Triangle

Overview of the pond



Dam



Maintenance Log Triangle

Riser



Inlet





Maintenance Log Triangle

Outlet



Additional Notes

Removed trash and debris from the system and treated terrestrial weeds. Noted images 1-3 show additional inlets. Notice the sediment from the riprap inlet in image 2.



Pond Name	WP 4
Access Address	501 Kildaire Rd, Chapel Hill, NC 27516
Trash Pickup	SC= Service Completed
Treat Invasives	M= Monitoring (for any potential future problems)
Inlet service	SC= Service Completed
Outlet Service	SC= Service Completed

Maintenance Log Triangle

Unclog Drain

M= Monitoring (for any potential future problems)

Clean Riser/Trash rack

M= Monitoring (for any potential future problems)

Add Dye?

N/A= Not Applicable

Fountain/Aerator Condition

M= Monitoring (for any potential future problems)

Mow/Weed eat

M= Monitoring (for any potential future problems)

Overview of the pond



Dam



Maintenance Log Triangle

Riser



Inlet



Maintenance Log Triangle

Outlet



Additional Notes

Removed trash from the system and cleared woody debris at the outlet. Noted images 1 and 2 show additional inlets.

